

TYPICAL HDPE CONNECTION TO GATE VALVE

- 1. WHERE GATE VALVE IS IN LINE WITH THE HDPE WATER MAIN, INSTALL D.I. PIPE THROUGH GATE WELL MAKING CONNECTION TO HDPE PIPE OUTSIDE OF GATE WELL AS SHOWN.
- 2. TRACER WIRES SHALL BE INSTALLED ALONG THE OUTSIDE OF THE GATE WELL AND BENEATH THE FRAME AND COVER.

- 1. SEE SHEET 2 OF THE WATER MAIN STANDARD DETAIL SHEETS FOR GENERAL TAPPING SLEEVE VALVE AND WELL DETAILS.
- 2. TAPPING SLEEVES FOR HDPE PIPE REQUIRE AN OUTLET SEAL GASKET AND SPRING WASHERS IN ADDITION TO THE REQUIREMENTS DETAILED IN SHEET 2 (JCM 452, ROMAC SSTH OR APPROVE EQUAL).


D.I. OR HDPE PIPE.

FOR TAPPING


STD DETAILS

CONCRETE PIPE


SEE SHEET 7 OF



CUT-IN HYDRANT TEE DETAIL



CUT-IN HYDRANT TEE DETAIL WITH 14" OR 10" HDPE



SERVICE LINE CONNECTION TO HDPE PIPE

1. FLARED HDPE SERVICE LINES ARE PROHIBITED.

